

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 1541
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

Jicarilla 390 B #1
Sec. 26, T23N, R4W
1850' FSL & 790' FWL
Sandoval County, New Mexico

SLOPE TEST

Depth

Hole Deviation

867'
1300'
1700'
2075'
2685'

1/4°
1/4°
3/4°
1/2°
3/4°

RECEIVED
NOV 28 1983
OIL CON. DIV.
DIST. 3

STATE OF NEW MEXICO)
) ss
COUNTY OF SAN JUAN)

I, Kevin H. McCord, Pet. Engineer, being first duly sworn,
depose and state that the above and foregoing depth and hole
deviation figures are true and correct to the best of my
information and belief.

Kevin H. McCord

Subscribed and sworn before me this 23rd day of November, 1983.

My Commission Expires 9-20-84.

William Hare
Notary Public