



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079248
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 26, 1954

Well No. 1 Hall is located 1650 ft. from N line and 1650 ft. from E line of sec. 8

N. 1/4 Sec. 8 (1/4 Sec. and Sec. No.) 23 N (Twp.) 12 W (Range) M. P. M. (Meridian)

Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation ~~of the derrick floor~~ above sea level is 6081 ft. g1

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Filled hole from TD to 50 with dirt and filled hole from 50 feet to surface with cement.
Set regulation marker, cleaned up and leveled location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company D & M Oil & Mining Company

Address Box 315

Cisco, Utah

By Charles R. North

Title Superintendent