(SÚBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office		
Land Onice	Santa	Fe
Lease No	08102	8-A

Unit _____ Flood #1

SUNDRY NO	TICES			<i>II</i>	JUL 1 8 1951
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SI NOTICE OF INTENTION TO RE-DRILL OR RI NOTICE OF INTENTION TO SHOOT OR ACII NOTICE OF INTENTION TO PULL OR ALTEI NOTICE OF INTENTION TO ABANDON WELL (INDICATE AB	HUT-OFF	SUBSEQUEN SUBSEQUEN SUBSEQUEN SUBSEQUEN SUPPLEMEN	T REPORT OF WATER STATE OF SHOOTING TO REPORT OF ALTERING TO REPORT OF ABANDON TARY WELL HISTORY. SEQUENT NOTE: NOT A STATE OF A ST	G CASING	
ORAL APPROVAL GRANT Well No is locate 1 Flood	3D 7/1 2/5 3df 990			July 16 rom $\{E \}$ line o	, 19
SE SE and Sec. No. 24 Wildcaffeld)	ZOM	Thereo		State or Territor	

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

was drilled to a total depth of 1348 ft.

Well was filled with heavy drilling mud. Capped surface casing and installed bleed off valve. Operations ceased temporarily.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company SULLIVAN & HILL Jack Sullivan, Operator 341 North Faothill Road Beverly Hills, Calif. R. D. Young, Agent