(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Po
Lease No	HMO3155

Unit 7-269 7-118

ALLIVED 1952

SUNDRY NOTICES AN	D REPORTS ON WELLS JUN 2 1952
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		******************	Yay	30 , 19 ⁰	
Well No. 1 service 11 is local	ed 990	ft. from \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	and ft. from	$\left\{\begin{array}{c} E \\ W \end{array}\right\}$ line of sec. 10	
W 14 Pag. 35	201	10	વૈક્ષાં પ્રાંતિક		
(½ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
(Field)	(County or Subdivision)		(8	(State or Territory)	

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The test was temperarily abundanced May 29th by spotting 20 and a of cement by Balliburton from 1892 to 1780. The demant severe as a boost first than soul and the top 13' of the statural CLISTS mediations.

ILLEGIBLE

I understar	id that this plan of work must receive approval in writing by the Company	Geological Survey before operations may be commenced.
	Mercentile decurities Building	
Address	Dallas	By By
	Texas	Title