


Finley & Johansen Nore #1
C - 22.29N-11W

This photograph was taken by Mr. Charles
Johnson, Oil Conservation Division Field Representative,
on April 4, 1978. This well is located in an
abandoned refinery yard in Bloomfield.

1. Open lines are potential sources of pollution.
2. Within 100 feet of residences.
3. Threat of pollution to other strata

Notified Don Ferguson of Plateau, Inc.
by phone 5-23-78.



2" tbg. @ unknown depth
rods in tbg. @ surface

COUNTY San Juan STATE NEW MEXICO
SEC. 22 T. 29N R. 11W
ELD OR AREA LOCATION 175'/N. 1570'/W
CASE Hare WELL NO. 1
COMPANY Finley & Johansen SPD. 7-25-34 COMPLETED 2-14-35
LEV. 5480' T. D. 722' P. B.
SING 10" @ 87' 8" @ 390' 6" @ 624'
BT OR ACID
F.
P.
PRODUCING FORM.
PRODUCTIVE DEPTH OR INTERVAL

REMARKS:

P&A

30-045-08166