


(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Navajo Tribal
Lease No. 1-149-IND-7653
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent report of D&T</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ May 13 _____, 19 52

Well No. Navajo 149 is located 1980 ft. from [N] line and 660 ft. from [E] line of sec. 34

NE 1/4 of Sec. 34 31-4 17-1 Maricopa
(Sec. and Sec. No.) (Twp.) (Range) (Municipality)
Wilcox San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 7373' Lime. On 5-11-52 took D&T 10 from 7300' to 7373'. Tool open 2 hrs. Small blow of air thruout test. Recovered 40' slightly Gas-cut mud, no show of oil. Flowing pressure 30%. 15 minute shut in B.H.P. - 285#. Hydrostatic pressure 4020#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address P.O. Box 12-1

Pampa, Texas

By [Signature]

Title Asst. Dist. Mgr.