

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-604-62

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Ute Indians

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Ute Indians "A"

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Ute Dome Dakota

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SW/4 NE/4 Section 2,

T-31-N, R-14-W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

AMOCO PRODUCTION COMPANY"

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1650' FNL & 990' FEL, Section 2, T-31-N, R-14-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6095.5' DF, 6094' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*


(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

As a result of the above well being unable to produce commercial quantities of gas, it  
was plugged and abandoned on August 6, 1976, as follows:

1. Pulled 1-1/4" tubing.
2. Squeezed 60 sacks cement from 2250' to 2200'.
3. Squeezed 20 sacks cement at 2700'.
4. Spotted 20 sacks cement plug from 1050' to 950'.
5. Set 40' plug at surface.
6. Erected abandonment marker.

We are waiting for your instructions for surface restoration.



RECEIVED

NOV 11 1976

U.S. GEOLOGICAL SURVEY  
WASHINGTON, D.C.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Adm. Supvr.

DATE

November 9, 1976

(This space for Federal or State office use)

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 12 1980

JOHN L. PRICE  
DISTRICT OIL & GAS SUPERVISOR

\*See Instructions on Reverse Side