

HONOLULU OIL CORPORATION

DRAWER 1391

MIDLAND, TEXAS

9-30-53 TD 7380. Ran electric logs to 7380

10-1-53 Core # 1 7380-7396. Recovered 16 feet. See Core record.

10-3-53 TD 7396. Lost circulation for 24 hours.

10-4-53 TD 7396. Lost circulation for 24 hours.

10-5-53 TD 7396. Lost circulation for 24 hours.

10-6-53 TD 7396. DST # 6 7234-7396. See DST record.

10-8-53 Core # 2 7396-7436. Recovered 40 feet. See Core Record.

10-11-53 TD 7545. Driving on stuck drill pipe.

10-12-53 TD 7545. Driving on stuck drill pipe.

10-15-53 Core # 3 7580-7624. Recovered 45 feet. See Core record.

10-17-53 Core # 4 7630-7670. Recovered 40 feet. See Core Analysis.

10-18-53 TD 7670. DST # 7 7634-7670. See DST record. Ran electric logs to 7670.

10-20-53 Core # 5 7670-7695. Recovered 25 feet. See Core Analysis.

10-21-53 TD 7695. DST # 8 7674-7695. See DST record.

10-22-53 Core # 6 7695-7719. Recovered 24 feet. See Core Analysis.
TD 7719. DST # 9 7688-7719. See DST record.

10-24-53 Core # 7 7719-7746. Recovered 26 feet. See Core Analysis.

10-25-53 Core # 8 7746-7771. Recovered 25 feet. See Core Analysis.

10-27-53 Core # 9 7771-7783. Recovered 12 feet. See Core Analysis.

10-28-53 Core #10 7783-7808. Recovered 25 feet. See Core Analysis.

10-29-53 Core #11 7808-7828. Recovered 16 feet. See Core Analysis.
TD 7828. DST # 10 7777-7828. See DST record.

10-31-53 Core # 12 7828-7860. Recovered 32 feet. See Core Analysis.

11-1-53 TD 7860. DST # 11 7834-7860. See DST Record. Ran electric logs to 7860.

11-2-53 TD 7860. DST # 12 7839-7845. Couldn't get to bottom. See DST record.

11-3-53 TD 7860. DST # 13 7839-7845. Couldn't get to bottom. See DST record.

