

30-045-6022 6

X Budget Bureau 42-R358.3.
Approval expires 12-31-55.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Alta Re
Lease No. 3 078635
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 19, 1953

Well No. 1 ^{Core Hole} is located 1650 ft. from NY line and 990 ft. from W line of sec. 14


100. 14. 30 4. 3. 15 4.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Alta Re San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Stratigraphic Test to the Pictured Cliffs Sandstone.
Projected depth 600 feet, plus or minus.
Cement surface pipe if necessary.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lucille H. Ripkin, Independent.

Address P.O. Box 117A

Roswell, New Mexico

By Lucille H. Ripkin


Title Owner

Company LUCILLE H. PIPKIN

Lease Cora Nole Well No. 21

Sec. 14, T. 30N, R. 15W

Location 1650 feet from south line; 990 feet
from west line.



Scale—4 inches equal 1 mile.

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Stephen H. Ruimy

Seal:

Registered Professional
Engineer and Land Surveyor.



Surveyed November 13, 1953