District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 ereno

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

						<b>OPERA</b>	OR		Initia	al Report		Final Report	
Name of Company Pure Resources						Contact Mike Northcutt							
Address P.O	. Box 609	Lovington,	NM 882	50		lephone No. Off 505-396-7503 Cell – 505-390-1090							
Facility Name Lovington San Adres Unit F							Facility Type – 2 Inch F.G. Lateral Line to Water Injection wells						
Surface Owner - City of Lovington NM Mineral Owner - S						State Lease No. B-1527							
Surface Country of Lovington 1919   Minual Country							Didic LAdSC NO. D-1321						
				LOCA	TION	OF REI	LEASE						
Unit Letter	Letter Section Township Range Feet from the Nor					South Line   Feet from the   East/			West Line   County				
J	31	16S	37E	2050'	South		1420	West		Lea			
			<u> </u>	L1				<u></u>	<del></del>				
		3	Latitude	- N32 degrees 5	2,631'	Longitud	e – W103 degr	ees 17,1	11'				
				NJ A TE	TIDE (	OE DET I	r a cie						
NATURE OF RELEASE  Type of Release – Produced Water with Iron Sulfide  Volume of Release – Est. 150										Volume Recovered – 540 bbls.			
Type of Release - Floduced water with from Suffice						bbls			Volume Reserved 5 vo bons.				
Source of Release - 2 inch fiber glass line						Date and Hour of Occurrence			Date and Hour of Discovery				
							8-20-05 11:00 AM 8-20-05 12:15 PM						
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Gary Wink NMOCD City of Lovington pumper						
		<u> </u>	I CS L	I NO LI NOLKE	danon								
By Whom?						Date and Hour 2:50P.Pm MST							
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
								<del> </del>					
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action. 2 inch fiber glass line parted at valve box glue separated and pulled out of connection. SI lines and isolated leak. Had 2-3 inches of rain the 8-18-05 which showed more water recovered than what was leaked. Also had 2 inches rain on 8-20-05, after													
picking up flu	iids.												
Describe Area										· · · · · · · · · · · · · · · · · · ·			
				getation. Produced									
			ere picked	by trucks and hau	led to di	sposal. Spil	l site will be teste	d and cle	aned up p	er NMOCD	regula	tions. Joint	
will be replace	ed before u	ısıng agaın.											
				is true and compl									
				nd/or file certain re									
				ce of a C-141 repo investigate and re									
				otance of a C-141									
federal, state,										•		•	
							OIL CON	SERV	ATION	DIVISIO	NC		
Signature: Mi	ika Narthar	144							62	212223	243		
Digitature, IVI	LLC 1 TOI UICE	***			——	۱	District Comment		100 m	A	SA SE S		
Printed Name	: Mike No	rthcutt			1	approved by	District Supervis	sor:	( <u>A</u>	Allo	•	$ec{oldsymbol{arepsilon}}/$	
								1/,	Spiration	AUG 2005		2829	
Title: SENM	Field Supe	rintendent				Approval Da	te:		Spiration	Desive	d	29	
E-mail Addre	ss: mnorth	cutt@nureres	ources cor	n	1	Conditions o	f Approval	/.	(3)	BZ997		930 G	
						- Justinosis U	approvar.	···········	163			4/	
									Mo,		-4.V)		
									1,0	87984	<u> </u>		