

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company EOG Resources, Inc.	Contact Zane Kurtz	
Address 5509 Champions Drive, Midland, TX 79706	Telephone No. 432-425-2023	
Facility Name Checkerboard '23' Federal CTB	Facility Type active well	
Surface Owner NM	Mineral Owner NM	API No. 30-025-31907

LOCATION OF RELEASE

Unit Letter O	Section 23	Township 22S	Range 32E	Feet from the 330	North/South Line S	Feet from the 1650	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.370980 **Longitude** -103.642371

NATURE OF RELEASE

Type of Release Crude Oil/produced Water	Volume of Release 40 bbls	Volume Recovered 40 bbls
Source of Release Oil Tank Overflow due to Plugged Water Leg	Date and Hour of Occurrence 1-18-2015	Date and Hour of Discovery 1-18-2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lease operator arrived on location on 18 January 2015 and noticed the oil tank was running over after evaluation water leg was plugged on heater treater. Operator called Production Foreman on call to advise, called vacuum truck to pick up standing fluids. CH2M HILL will collect soil samples on behalf of EOG Resources, Inc. on 26 January 2015 to delineate vertical and horizontal impacts.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz	Hydrologist Approved by Environmental Special	
Title: Sr. Environmental Representative	Approval Date: 01/30/2015	Expiration Date: 03/30/2015
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD	Attached <input type="checkbox"/> 1RP-3520 7377
Date: 1/26/2015 Phone: 432-425-2023	nTO1503042807 pTO1503042948	

* Attach Additional Sheets If Necessary

guides. Submit final C-141 by
03/30/2015