

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	XOG OPERATING, LLC	Contact	ANGIE CRAWFORD
Address	1801 W. TEXAS, MIDLAND, TX 79702	Telephone No.	432-683-3171
Facility Name	SIMS 35 STATE	Facility Type	BATTERY
Surface Owner	STATE OF NM/SIMS RANCH	Mineral Owner	
		API No.	30-025-27785

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	20s	35E	1980	NORTH	1980	EAST	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Production Fluids	Volume of Release	10 BW, 1 BO	Volume Recovered	9 BW, 1 BO
Source of Release	Tank overflow	Date and Hour of Occurrence		Date and Hour of Discovery	12/11/14
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Rancher Reported to NMOCD and Bill Sonnamaker With NMOCD Contacted XOG.			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Seperator malfunction. Shut-in well, vacuum up standing fluids and repair seperator .

Describe Area Affected and Cleanup Action Taken.*

1RP-3463. 10' x 10' on NE side, inside firewall. Removed contaminated soil to a depth of two feet. Sent contaminated soil to Lazy Ace Land Farm. Cardinal Laboratories took samples and ran analysis at excavation site. Results emailed to Tomas Obering, EMNRD. Hauled clean soil and filled excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Angie Crawford	Hydrologist	
Title: Production/Regulatory Analyst	Approved by Environmental Specialist	
E-mail Address: acrawford@xogoperating.com	Approval Date: 02/02/2015	Expiration Date:
Date: 2/2/15 Phone: 432-683-3171	Conditions of Approval:	Attached <input type="checkbox"/> 1RP_3463

* Attach Additional Sheets If Necessary