<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release	<b>Notification</b>	and (	Corrective	Action
ILCICUSC	1 10 millounom	uiiu		110111

						<b>OPERATOR</b>   Initial F						Fina	al Report
Name of Company: COG Operating LLC						Contact: Robert McNeill							
Address: 600 West Illinois Avenue, Midland TX 79701						Telephone No. 432-230-0077							
Facility Name: Pintail 3 Federal SWD #1					Facility Type: Battery								
Surface Ow	Surface Owner: Federal Mineral Owner					r: API No. 30-025-41208							
				LOCA	TIO	N OF REI	FASE		1				
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/W	Vest Line		Coun	tv	
J	3	26S	32E	2500		South	1400		East		Lea	•	
			Lati	tude32.0719317	4023	84 <b>Longitud</b>	e -103.65874416	63143					
				NAT	URE	E OF RELI	EASE						
	Type of Release:					Volume of Release: Volume Recovered:							
	Produced Water Source of Release:					125 bbls   0 bbls   Date and Hour of Occurrence: Date and Hour of Discovery:							
	Illegal Dumping					1/17/2015 10:00 am 1/17/2015 10:00 am							
Was Immedia				_			If YES, To Whom?						
			Yes	No Not Rec	quired	l Dr. Oberdi	Dr. Oberding – NMOCD / Mr. Amos – BLM						
	By Whom? Lupe Carrasco					Date and Hour: 1/19/2015 12:32 pm							
Was a Water	course Reach	ied?	Yes 🛚	l No		If YES, Volume Impacting the Watercourse.							
IC W	<b>T</b>	_											
If a Watercou	irse was impa	acted, Descri	be Fully.	•									
Describe Cau	use of Duobles	m and Damad	lial Astice	Tolson *									
				1 1 aken.* f produced water b	ov wat	er hauler. A fe	nce was knocked	down in	the incider	nt.			
111101010400	us caused o	y un megur a	umping o	produced water c	<i>y</i>		nee was missenee						
Describe Are	a Affected at	nd Cleanup A	ction Tak	an *									
Describe 7 tre	a miceted ai	nd Cleanup 7	ction ran	cii.									
	The impacted area was confined to the pad area. Concho will have the spill site sampled to delineate any possible contamination from the release and we								nd we				
will present a	remediation	work plan to	the NMC	OCD for approval p	prior t	to any significa	nt remediation wo	ork.					
				is true and comple									
1	- · · · · ·		-	id/or file certain re						_			
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
				tance of a C-141 r									
federal, state.	or local law	s and/or regu	lations.		•		•	•		•			
		,					OIL CONSERVATION DIVISION						
Signature:		- Lujelle		le.			Hydrologist						
Signature.					Approved by Environmental Specialist:						P	80	
Printed Name	e: Amanda T	rujillo				ripproved by	Environmental S <sub>1</sub>	pecialist	/				
Title: Senior	Environment	al Coordinat	or			Approval Dat	e: 02/03/2015	5 E	Expiration I	Date: 04	/03/20	015	
E mo:1 4.4.4	2001 otm:::11c 6	Maanaha as:				Conditions -4	· Annroyel.						
E-man Addre	E-mail Address: atrujillo@concho.com					Site sam	Approval: oles required.	Delin	eate	Attached			
	Date: February 2, 2015 Phone: 575-748-6940					and remediate are as per NMOCD 1RP-3521							
Attach Additional Sheets If Necessary guides. 229								29137					
	Submit final C-141 by 04/03/2015 pTO1503427166												
						IIII I	5 1 1 1 0 y	5 1, 05	515	P1013	0014	, 100	,