

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Jay Management Company	Jim Foster	
2425 W Loop South Suite 810, Houston Texas 77027	979-324-2139	
Facility Name: New Mexico BB State No. 1 Tank Battery	Facility Type: Tank Battery	
Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No.

LOCATION OF RELEASE

Unit Letter	Section 14	Township 10S	Range 32E	2200 Feet from the	North Line	3300 Feet from the	West Line	Lea County
-------------	---------------	-----------------	--------------	-----------------------	------------	-----------------------	-----------	------------

Latitude: 33° 26.657' **Longitude:** 103° 38.420'W

NATURE OF RELEASE

Type of Release: Crude oil and Produced Water	Volume of Release: 8 bbl	Volume Recovered: 5 bbl
Source of Release: Overflowed water tank	Date and Hour of Occurrence 1/23/2015 – Time not known	Date and Hour of Discovery: 1/23/2015 9:00 am
Was Immediate Notice Given? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

*If a Watercourse was Impacted, Describe Fully.**
No watercourse was impacted.

*Describe Cause of Problem and Remedial Action Taken.**

Release occurred due to the water tank overflowing. All released fluids were contained by firewall. Oil was recovered by vacuum truck on 07/23/2015.

*Describe Area Affected and Cleanup Action Taken.**

The affected area is the immediately area surrounding the tanks. The release was contained by the facility's firewall. A vacuum truck was called and to recover fluids that morning (01/23/2015).

Much of the impacted soil at this battery is a result of historic releases from the facility. Impacted soils will be removed and properly disposed in the coming weeks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:  Jim Foster Consultant	OIL CONSERVATION DIVISION	
	Hydrologist Approved by Environmental Specialist	
	Approval Date: 02/13/2015	Expiration Date: 04/13/2015
E-mail Address: jim.foster@twolfenv.com	Conditions of Approval: Site samples required. Delineate and remediate as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3536 247692
Date: 02/03/2015 Phone: (979) 324-2139		

* Attach Additional Sheets If Necessary

nTO1504431334
pTO1504431549