

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: QPQASU #24	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-025-25618
--------------------	--------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter E	Section 27	Township 18S	Range 32E	Feet from the 2310'	North/South Line North	Feet from the 1980'	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	---------------

Latitude 32.7193295 Longitude -103.756283

#### NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 10 bbls	Volume Recovered: N/A
Source of Release: Stuffing box/well head	Date and Hour of Occurrence 5-19-15	Date and Hour of Discovery 5-19-15 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones - NMOCD	
By Whom? Zack Thomas	Date and Hour 5-19-15 2:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**REVIEWED**

**By OCD District 1 at 7:42 am, May 21, 2015**



Describe Cause of Problem and Remedial Action Taken.\*

Well was shut-in and pumping unit turned off due to production practices, but pumping unit was turned on by an anonymous party causing stuffing box to blow out due to tubing and casing valves being shut. Pumping unit was turned back off by pumper upon arrival to stop the release.

Describe Area Affected and Cleanup Action Taken.\*

Leaked fluid affected the well pad surface around pumping unit and also ran west of the pad out into the pasture an estimated 35 yards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 05/21/2015	Expiration Date: 08/21/2015
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 14744 1RP-3643
Date: 5-20-15 Phone: 575-602-2188		

\* Attach Additional Sheets If Necessary

pKJ1514129031  
nKJ1514128176







