

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company	Oxy Permian	Contact	Tony Aguilar
Address	1017 W. Stanolind Road	Telephone No.	575-397-8251
Facility Name	NHU 24-342	Facility Type	Injection Trunk line
Surface Owner	Mineral Owner	Lease No. 30-025-29062	

LOCATION OF RELEASE

Unit Letter	Section 25	Township 18-S	Range 37-E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	--------

Latitude_N. 32.721561 Longitude_W 103.204495

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	145 bbls	Volume Recovered	45 bbls
Source of Release	4" steel injection trunk line	Date and Hour of Occurrence	5-10-15 @ 10:30am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding by email on 5-10-15		
By Whom?	Tony Aguilar	Date and Hour	5-10-15 @ 12:19 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*	<div>RECEIVED By OCD District 1 at 9:38 am, May 29, 2015</div>				



Describe Cause of Problem and Remedial Action Taken.*

4" steel line leaked due to internal corrosion, leaking around 145 bbl. of produce water onto the ground. 45 bbl. were recovered via vacuum truck and as of 5-28-15 the line is being repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 110' x 325' on location. Remediation will be completed in accordance with a plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Tony Aguilar	Approved by District Supervisor: 		
Title: HES Specialist	Approval Date: 05/29/2015	Expiration Date: 08/29/2015	
E-mail Address: Raymond_aguilar@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/> 157984 1RP-3653
Date: 5-28-15 Phone: 575-397-8251	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		

- Attach Additional Sheets If Necessary

pKJ1514936418
nKJ1514934862