

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: SOGO III LLC	Contact: Bill Priebe	
Address: PO Box 210 Midland, Tx 79702	Telephone No.: 432-640-0040	
Facility Name: Wimberly 5, 6, 7	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No.: 30-025-24482

LOCATION OF RELEASE

Unit Letter G	Section 12	Township 24	Range 32	Feet from the 660	North/South Line NL	Feet from the 660	East/West Line EL	County Lea County
------------------	---------------	----------------	-------------	----------------------	------------------------	----------------------	----------------------	----------------------

Latitude: 32.2376546 Longitude: -103.6389687

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 78	Volume Recovered: 5
Source of Release: Tank Overflow	Date and Hour of Occurrence: 03/26/2015	Date and Hour of Discovery: 03/26/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson - BLM	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 03/26/15-1600 hrs	

If a Watercourse was Impacted, Describe Fully.*: Tank overflow. Initial response was to remove free standing fluid from the surface to prevent further vertical migration. Impacted soils were stored on location for disposal.

RECEIVED

By OCD District 1 at 2:00 pm, Jun 10, 2015

Describe Cause of Problem and Remedial Action Taken.*: Tank overflow. Initial response was to remove free standing fluid from the surface to prevent further vertical migration. Impacted soils were stored on location for disposal.

Describe Area Affected and Cleanup Action Taken.*: Tank overflow impacting 740' of caliche road approximately 6' wide, and impacting the pasture area 12'X10'.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Bill M. Priebe</i>	Approved by District Supervisor: <i>[Signature]</i>	
Printed Name: <i>Billy M. PRIEBE</i>	Approval Date: <i>06/10/2015</i>	Expiration Date: <i>09/10/2015</i>
Title: <i>Ex. VP - OPERATIONS</i>	Conditions of Approval: <i>Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.</i>	
E-mail Address: <i>bpriebe@stanolind.com</i>	Attached <input type="checkbox"/> <i>309220</i>	RP-3666
Date: <i>5/6/15</i>	Phone: <i>432-640-0040</i>	

* Attach Additional Sheets If Necessary

nKJ1516249669
pKJ1516249927