

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	APPROVED Ensure BLM Concurrence By OCD District 1 at 3:19 pm, Jun 11, 2015
Facility Name Rosemary SWD #1	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-31227
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter L	Section 6	Township 22S	Range 32E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.41862 Longitude 103.72031



NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 50 B/O	Volume Recovered 45 B/O
Source of Release Production Tank	Date and Hour of Occurrence 3/24/2015; AM	Date and Hour of Discovery 3/24/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding, PhD/NMOCD I	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 3/25/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*	RECEIVED By OCD District 1 at 3:19 pm, Jun 11, 2015
Describe Cause of Problem and Remedial Action Taken.* The production tank overflowed, causing the release. Vacuum truck(s) were called.	

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 40'X 20' within the lined and bermed battery. The valves were closed and most of the spill was recovered using a vacuum truck (45 B/O). Remaining oil was entrained within gravel; impacted gravel was removed /hailed to a NMOCD approved facility. **Depth to Ground Water: >100' (approximately 325', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on the battery being lined/bermed and 90% of the released crude oil recovered (remaining oil was disposed with impacted gravel), Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Asher		Hydrologist	06/11/2015
Title: NM Environmental Regulatory Supervisor		Approved by Environmental Specialist: 	
E-mail Address: boba@yatespetroleum.com		Approval Date: 04/10/2015	Expiration Date: ///
Date: April 8, 2015	Phone: 575-748-4217	Conditions of Approval: 2RP- Provide photographic support.	Attached <input type="checkbox"/> 1RP-3596 25575

* Attach Additional Sheets If Necessary

nTO1510028800

pTO1510028961

