

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	(432) 686-3667
Facility Name	Falcon Federal 25 #2H	Facility Type	Oil Well
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-41418

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	24	24S	33E	1050	South	250	West	Lea

Latitude 32.1820 Longitude -103.5312

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	Approx. 20 bbls	Volume Recovered	0 BBLs
Source of Release	Poly line rupture	Date and Hour of Occurrence	6/22/15 8:00 am	Date and Hour of Discovery	6/22/2015 at approximately 10:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
<div>RECEIVED By OCD District 1 at 1:04 pm, Jun 23, 2015</div>					



Describe Cause of Problem and Remedial Action Taken.*

A poly line had broken apart at a seam due to over pressure. The line was repaired upon discovery.

Describe Area Affected and Cleanup Action Taken.*

Approximately 20 BBLs of produced water were released. No fluids were able to be recovered. Assessment and excavation of the soil in the area will take place in the near future.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: BERNARD BOCKISCH	Approved by Environmental Specialist: 		
Title: CONSULTANT FOR EOG RESOURCES	Approval Date: 06/23/2015	Expiration Date: 09/23/2015	
E-mail Address: BBOCKISCH@CRAWORLD.COM	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCDC guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 7377 IRP-3686
Date: 6/23/15	Phone: 505-884-0672		

* Attach Additional Sheets If Necessary

nKJ1517447251
pKJ1517447382