

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Brian Kuh
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 616-1540
Facility Name: Rattlesnake 13-12 Fed Com 1H	Facility Type : 0.1 miles south of location

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-40912
-------------------------------	-------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter P	Section 13	Township 26S	Range 34E	Feet from the 330	North/South Line South	Feet from the 330	East/West Line East	County Lea
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude: **32.036958** Longitude: **103.416218**

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 bbls	Volume Recovered: 17 bbls
Source of Release: Lay Flat Water Transfer Line	Date and Hour of Occurrence 6/13/15, 3:00 PM	Date and Hour of Discovery 6/13/15, 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jim Amos	
By Whom? Brian Kuh, Devon Foreman	Date and Hour: 6/13/2015, 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Two punctures in the treated water transfer line approximately one foot apart caused the leak. Immediately, the crew pinched the line and utilized absorption pads, a vacuum truck, preventive flow devices, and a tele-handler wheel path to contain the spill and recover all but 1 barrel.

Describe Area Affected and Cleanup Action Taken.*

3.5 feet x 20 feet off location and not contained. Talon will take soil samples and prepare a remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 06/24/2015	Expiration Date: 09/24/2015
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 6137 IRP-3689
Date: 6/16/2015 Phone: 575-746-5544		

* Attach Additional Sheets If Necessary

RECEIVED

By OCD District 1 at 11:25 am, Jun 24, 2015

nKJ1517541266

pKJ1517541608

13-26S-34E
SESE

18-26S-35E
Lot 4
40.9 ac

24-26S-34E
NENE

19-26S-35E
Lot 1
40.93 ac

24-26S-34E
SENE

19-26S-35E
Lot 2
40.95 ac

Rattlesnake 13-12 Fed Com 1H

28 BBL PW Spill

Devon GIS Mapping



Disclaimer: This plat is for illustrative purposes only and is neither a legally recorded map nor a survey and is not intended to be used as one.

Scale: 1:4,514

Date Printed: 6/18/2015 12:06:27 PM