

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jay Garcia</b>	
Address: <b>29 Vacuum Complex Lane</b>	Telephone No. <b>575-704-2455</b>	
Facility Name: <b>Vac Abo # 04</b>	Facility Type: <b>Trunk Line</b>	
Surface Owner: <b>NMOCD</b>	Mineral Owner:	API No. <b>30-025-26931</b>

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	05	18S	35E	2286	North	2080	West	LEA

Latitude 32.7779083,- Longitude 103.4816513

### NATURE OF RELEASE

Type of Release: <b>Spill</b>	Volume of Release: 1 BO & 22.23 BPW	Volume Recovered. 5 BPW
Source of Release: <b>Trunk line leak.</b>	Date and Hour of Occurrence 07/06/2015 5:45 am	Date and Hour of Discovery 07/06/2015 5:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Tomas Oberding- NMOCD</b>	
By Whom? <b>Jay Garcia</b>	Date and Hour: <b>07/06/2015 2:30 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <div style="border: 1px solid black; padding: 5px; display: inline-block;"><b>RECEIVED</b> By OCD; Dr. Oberding at 3:47 pm, Jul 06, 2015</div>		

ENV – Agency Reportable – 1 BO & 22.23 BPW – Vac Abo 04 – RR II – MCBU – Buckeye – On Monday July 06, 2015 at 0540 MDT, a release occurred at Vac Abo Battery 4. MSO responded to a trunk line leak resulting in a release of 1 BO and 22.23 BPW with 5 BPW recovered. Immediate action was to shut down wells and facility and close valve to trunk line. A work order has been submitted for repairs. The affected area will be remediated according to NMOCD and COPC and guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jay Garcia		Approved by Environmental Specialist: <i>[Signature]</i> PhD	
Title: LEAD HSE		Approval Date: 07/06/2015	Expiration Date: 10/06/2015
E-mail Address: <b>jay.c.garcia@conocophillips.com</b>		Conditions of Approval: Site samples required. Delineate and remeadiated as per OCD guides. Please provide geotagged photos of remediation.	
Date: 07/06/2015 Phone: 575-704-2455		Attached <input type="checkbox"/> 1RP-3714 217817	

\* Attach Additional Sheets If Necessary

nTO1518757703

pTO1518936962