

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: SOGO III LLC	Contact: Bill Priebe	
Address: PO Box 210 Midland, Tx 79702	Telephone No.: 432-640-0040	
Facility Name: Wimberly 5, 6, 7	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No.: 30-025-24482

LOCATION OF RELEASE

Unit Letter G	Section 12	Township 24	Range 32	Feet from the 660	North/South Line NL	Feet from the 660	East/West Line EL	County Lea County
------------------	---------------	----------------	-------------	----------------------	------------------------	----------------------	----------------------	----------------------

Latitude: 32.2376546 Longitude: -103.6389687

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 78	Volume Recovered: 5
Source of Release: Tank Overflow	Date and Hour of Occurrence: 03/26/2015	Date and Hour of Discovery: 03/26/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson	
By Whom?	Date and Hour: 03/26/15 - 1600 hrs.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*: Hole in tank from corrosion. Initial response was to remove free standing fluid from the surface to prevent further vertical migration. Impacted soils were stored on location for disposal.		

APPROVED

By OCD District 1 at 1:56 pm, Jul 13, 2015

Describe Cause of Problem and Remedial Action Taken.*: Hole in tank from corrosion. Initial response was to remove free standing fluid from the surface to prevent further vertical migration. Impacted soils were stored on location for disposal.

Describe Area Affected and Cleanup Action Taken.*: Release impacted 740' of caliche road approximately 6' wide, and impacting the pasture area 12'X10'. Excavated soils were transported off-site for disposal. Sampling confirmed clearance for pasture area at less than 500 mg/kg and less than 1,000 for road area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Billy M. Priebe</i>	OIL CONSERVATION DIVISION	
Printed Name: Billy M. Priebe	Approved by District Supervisor: <i>[Signature]</i>	
Title: Ex. VP - Operations	Approval Date: 07/13/2015	Expiration Date: //
E-mail Address: bpriebe@stanolind.com	Conditions of Approval: //	Attached <input type="checkbox"/> IRP-3666
Date: 5/15/15	Phone: 432-690-0040	

* Attach Additional Sheets If Necessary

RECEIVED

By OCD District 1 at 1:55 pm, Jul 13, 2015