

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Cimaxex Energy	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Southern California 29 Fed 15	Facility Type production

Surface Owner BLM	Mineral Owner	API No. 30-015-39634
-------------------	---------------	----------------------

**LOCATION OF RELEASE**

30-025-39634

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	29	19S	32E	375	S	330	W	Lea

Latitude 32.6252 Longitude -103.7958

**NATURE OF RELEASE**

Type of Release produced water	Volume of Release 15 bbls	Volume Recovered 12 bbls
Source of Release poly flowline	Date and Hour of Occurrence 7/22/2015	Date and Hour of Discovery 7/22/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 7/23/2015 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 1:03 pm, Jul 30, 2015

Describe Cause of Problem and Remedial Action Taken.\*

A 3" poly flow line that runs along lease road from this battery to the SWD appeared to have been run over and split. All fluids were on lease road.

Describe Area Affected and Cleanup Action Taken.\*

Approx 12' x 12' area. Road had been bladed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>Janet Hays</i>	
Title: ESH Supervisor	Approval Date: 07/30/2015	Expiration Date: 09/30/2015
E-mail Address: calderman@cimaxex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/30/2015 Phone: 432-853-7059	Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos of remediation required. Ensure BLM concurrence/approval.	IRP 3774

\* Attach Additional Sheets If Necessary

nJXK1521147061  
pJXK1521147209