

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jay Garcia
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455
Facility Name: EVGSAU Satellite #05	Facility Type: Well

Surface Owner: NMOCD	Mineral Owner:	API No. 30-025-26395
-----------------------------	----------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	26	17S	35E	2496	North	1544	West	LEA

Latitude 32.8062592 **Longitude** 103.431839 NAD83

NATURE OF RELEASE

Type of Release: Leak	Volume of Release: 31 bbl. produces water & 1 bbl. of oil	Volume Recovered. 39 bbl. produced water & 1 bbl. of oil due to rain storm.
Source of Release: Transfer pump leak	Date and Hour of Occurrence 08/03/2015 3:30 am	Date and Hour of Discovery 08/03/2015 3:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Jay Garcia	Date and Hour: 08/03/2015 3:10 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 7:22 am, Aug 04, 2015

ENV – Agency Reportable – 31 BPW & 1BO – EVGSAU Satellite 5 – RR II – MCBU – Buckeye – On Monday August 03, 2015 at 0330 MDT, at EVGSAU Satellite 5, MSO received a callout for EVGSAU Satellite 5 shutdown. MSO arrived on location and observed transfer pump had failed resulting in a release of 31 bbls of produced water and 1 bbl of oil, with 29 bbls of produced water and 1 bbl of oil recovered. 10 bbls of rainwater was also recovered in addition to the released fluid. Immediate action was to isolate the pump and turn in a work order for repair and remediation. The affected area will be remediated according to NMOCD and COPC guidelines. This is a Tier 3 PSE.

Consequence: 2 Likelihood: 3 RR: 2

Describe Area Affected and Cleanup Action Taken.*

A discharge of 31BPW & 1BO occurred with 40BBLS recovered with 10 of those BBLS being rainwater. Spill area was 180' X 20', 1/2" deep on caliche pad. Spill area will be remediated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Jay Garcia*

Printed Name: Jay Garcia

Approved by Environmental Specialist:

Jamie Hoyer

Title: LEAD HSE	Approval Date: 08/04/2015	Expiration Date: 10/04/2015
E-mail Address: <i>jay.c.garcia@conocophillips.com</i>	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required. Ensure SLO concurrence/approval	Attached <input type="checkbox"/> ogrid 217817 1RP 3775
Date: 08/03/2015 Phone:575-704-2455		

* Attach Additional Sheets If Necessary

pJXK1521626889 nJXK1521626690