

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	Marshall & Winston, Inc.	Contact	Todd Passmore
Address	P.O. Box 50880, Midland, TX 79710-0880	Telephone No.	432-894-0165 or 432-684-6373
Facility Name	Klein 16 St. #2H	Facility Type	Well Location & Battery

Surface Owner	Alta Faye Klein c/o George L. Klein	Mineral Owner	State of New Mexico	API No.	30-025-40852
---------------	--	---------------	---------------------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	19S	35E	660	North	250	East	Lea

Latitude 32.665896 Longitude 103.454141

**NATURE OF RELEASE**

Type of Release	Oil & Water	Volume of Release	45 bbls	Volume Recovered	40 bbls
Source of Release	Heater Treater	Date and Hour of Occurrence	08/12/15	Date and Hour of Discovery	08/12/15 2PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Ian Dolly		
By Whom?	Travis Flemmons	Date and Hour	08/12/15 3:30 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 2:06 pm, Aug 14, 2015



Describe Cause of Problem and Remedial Action Taken.\*

Blown gasket in the fire tube in the heater treater.  
Pick up all free standing fluid with vac. truck.

Describe Area Affected and Cleanup Action Taken.\*

Caliche around heater treater on well location.  
See attachment for proposed plan of action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:					
Printed Name:	Tom M. Brandt	Approved by Environmental Specialist:			
Title:	President	Approval Date:	08/14/2015	Expiration Date:	10/14/2015
E-mail Address:	tbrandt@mar-win.com	Conditions of Approval:	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		
Date:	08/14/15	Phone:	432-684-6373	Attached	<input type="checkbox"/> 1RP-3800

\* Attach Additional Sheets If Necessary

nKJ1522656396  
pKJ1522656560

**RECEIVED**

By OCD District 1 at 2:07 pm, Aug 14, 2015

**APPROVED** Conditional

By OCD District 1 at 2:07 pm, Aug 14, 2015

1. Due to this being a PW/Oil spill, chlorides will need to be tested, along with BTEX.
2. Ensure confirmation samples are taken.

3302 122nd Street  
Lubbock, Texas 79423  
Mailing Address:  
P.O. Box 53427  
Lubbock, Texas 79453  
Phone: 806-771-8033  
Fax: 806-687-6926  
www.bccccorp.com



August 14, 2015

Mr. Todd Passmore  
MARSHALL & WINSTON, INC.  
P.O. Box 50880  
Midland, TX. 79710-0880

RE: Klein 16 State 2H Unit A, Sec. 16-T19S-R35E Lea County, New Mexico

Mr. Passmore,

BCC, Inc. proposes the following plan of action for the reportable surface release off of the Klein 16 State 2H battery:

Removal of all impacted soils on location and in affected pasture areas until a representative sample at the base of excavation is below the specific remediation level approved. All excavated material will be placed on an impermeable liner and disposed of at an off-site permitted facility. Clean soil located on site will be backfilled and incorporated with both nutrients and fresh water into the excavated areas.

All soil samples pulled will be laboratory analyzed for total petroleum hydrocarbons at an OCD approved facility. A GPS track map, digital pictures, and soil sample documentation will be provided to you at the completion of this project. Please let me know if you need any other information regarding this matter and I will make it available to you.

Sincerely,

Paul Porter  
Vice President