

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By OCD District 1 at 11:02 am, Aug 31, 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company EOG Resources, Inc.	Contact Zane Kurtz	
Address 5509 Champions Drive, Midland, TX 79706	Telephone No. 432-425-2023	
Facility Name Short Fuse Fed #1	Facility Type Oil and Gas Well and Tank Battery	
Surface Owner BLM	Mineral Owner EOG Resources	API No. 30-025-29897

**LOCATION OF RELEASE**

Unit Letter H	Section 11	Township 18S	Range 32E	Feet from the 2036	North/South Line N	Feet from the 613	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	----------------------	---------------------	---------------

Latitude 32.7636 Longitude -103.7306

**NATURE OF RELEASE**

Type of Release Produced Water/Oil	Volume of Release 5 bbls	Volume Recovered 0
Source of Release Steel elbow on inlet to Heater failed	Date and Hour of Occurrence 8/16/2015	Date and Hour of Discovery 8/16/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.*		
<div><b>APPROVED</b> By OCD District 1 at 11:02 am, Aug 31, 2015</div>		



**Describe Cause of Problem and Remedial Action Taken.\***

Elbow on piping failed and leaked out about 5 bbls of produced water with some oil. Pumper immediately closed valve to stop release. Called clean up crew to remove impacted soil. Once they started removing impacted soil, they found impacted soil from historical release that reached into the pasture about 50 feet. They removed about 100 yards of soil and disposed of at Lea Land Disposal in Carlsbad, NM. Then replaced with clean backfill from pit at the entrance of lease area.

**Describe Area Affected and Cleanup Action Taken.\***

Environmental Dept. did not realize extent of impacts. 3<sup>rd</sup> party Consultant will go to site and collect soil samples to see if impacted soil has all been removed. If not, they will excavate impacted soil and place on poly liner for proper disposal. Clean soil will then be used for backfill. A work plan will be submitted to the OCD and BLM to make sure archeological survey has been completed for area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Zane Kurtz, EOG Resources	Approved by Environmental Specialist: 		
Title: Sr. Environmental Rep.	Approval Date: 08/31/2015	Expiration Date: 10/31/2015	
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 3832
Date: 8-27-2015	Phone: 432-425-2023		

\* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.  
Ensure BLM concurrence/approval.

pJXK1524339663  
nJXK1524339508