<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Santa 1 C, TVVI 67505													
Release Notification and Corrective Action													
						OPERATOR							
Name of Co	ompany D	evon Energy	Contact Dan Suniga										
							Telephone No. 575.390.5850						
Facility Name Tomcat 17 Federal 1						Facility Ty	pe Oil						
Surface Ov	vner Fede	ral	· Federal			API No. 30-025-34690							
				LOCA	TIO	N OF REI	LEASE						
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
P	17	23S	32E	660	1,010	FSL	660	FEL		LEA			
Latitude: 32.299008 Longitude: 106.689833 NATURE OF RELEASE													
Type of Release Spill Oil							Volume of Release 90 BBL			Volume Recovered 10 BBL			
Source of Release Hole at the bottom of oil tank							Date and Hour of Occurrence 8/26/15 11:00 am			Date and Hour of Discovery 8/26/15 11:00 am			
Was Immediate Notice Given?							O/20/15 11:00 am						
✓ Yes ☐ No ☐ Not Required													
By Whom? Ray Carter							Date and Hour						
							8/26/15 11:15 am BLM						
							8/26/15 11:20 am OCD						
Was a Wate	rcourse Re		If YES, Volume Impacting the Watercourse										
☐ Yes ⊠ No							RECEIVED						
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.* By OCD District 1 at 12:30 pm, Aug 31, 2015													
On 8/26/15 at the Tomcat 17 Fed 1 an oil tank had a hole at the bottom of tank causing a spill all in containment. The well was shut in and a													
vendor was called out to empty all oil tanks into frac tanks.													
Describe Area Affected and Cleanup Action Taken.*													
A 90 BBL oil spill and 10 BBL recovered on a 30' X 100' area in unlined containment. An environmental company will be called out to evaluate													
area.													
I hereby certi	fy that the i	nformation gi	ven above	e is true and comp	lete to t	he best of my	knowledge and u	ınderstand t	hat purs	suant to NM	OCD r	ules and	
				nd/or file certain r									
				ce of a C-141 repo									
				investigate and r									
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
lederal, state,	or local lav	ws and/or regu	nations.				OIL CON	CEDVA	TION	DIVICIO	\\T		
Signature: Jeanette Barron							OIL CONSERVATION DIVISION						
Signature. J		DUTTOTO					,						
Printed Name: Jeanette Barron							Approved by Environmental Specialist:						
Title: Field A	dmin Sup	port				Approval Da	te: 08/31/2015	Exp	oiration l	Date: 10/3	1/2015		
E "	.					C 11:1							
E-mail Address: Jeanette.barron@dvn.com						Conditions of Approval: Site correctors are a series of Attached 6137					6137		
Date:	8/28/15		Site samples required. Delineate and 1RP-3833										

Phone: 575.748.1813

8/28/15

Tomcat 17 Federal 1 90 BBL oil spill 10 BBL recoverd



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere Prepared by: Jeanette Barron Map is current as of: 28-Aug-2015



Miles

0.04 1:1,779

TDM Wells (Drilled) TDM Wells (Proposed)











