

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By OCD District 1 at 8:52 am, Sep 02, 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Gunner 8 State SWD #1	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-025-40890
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 16	Township 26S	Range 34E	Feet from the 330'	North/South Line North	Feet from the 330'	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude Longitude

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 150 bbls PW	Volume Recovered: 148 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 7/24/2015 5:00 pm	Date and Hour of Discovery: 7/24/2015 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Wed 7/29/2015 6:50 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By OCD District 1 at 8:52 am, Sep 02, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was by a 6" flowline on a gun barrel. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined containment. The facility was cleaned repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 09/02/2015	Expiration Date: ///	
E-mail Address: atrujillo@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: August 20, 2015 Phone: 575-748-6940	///		IRP 3838

* Attach Additional Sheets If Necessary

