

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By OCD District 1 at 2:38 pm, Sep 02, 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Stratojet 31 State Com #6H	Facility Type: Battery	
Surface Owner: State	Mineral Owner:	API No. 30-025-42452

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	31	20S	35E	390'	South	2080'	East	Lea

Latitude 32.52328667 Longitude -103.49428778

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls Oil	Volume Recovered: 1 bbl Oil
Source of Release: Dump valve	Date and Hour of Occurrence: 8/8/2015 8:00 am	Date and Hour of Discovery: 8/8/2015 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By OCD District 1 at 2:38 pm, Sep 02, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a dump valve failed and oil was sent to the flare. Crews were dispatched immediately to apply soapy water and Microblaze.

Describe Area Affected and Cleanup Action Taken.*

This release impacted the nearby pasture with a mist in an area approximately 300 x 900'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 09/02/2015	Expiration Date: 11/02/2015	
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 3840
Date: August 22, 2015 Phone: 575-748-6940	Geotagged photos of remediation required.		

* Attach Additional Sheets If Necessary

pJXK1524552564

nJXK1524552463