

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company EOG Resources, Inc.	Contact Zane Kurtz	
Address 5509 Champions Drive, Midland, TX 79705	Telephone No. 432-425-2023	
Facility Name Diamond 31 Fed Com #1 SWD	Facility Type Salt Water Disposal well	
Surface Owner BLM	Mineral Owner EOG Resources	API No. 30-025-40484

LOCATION OF RELEASE

Unit Letter G	Section 31	Township 24S	Range 34E	Feet from the 3323	North/South Line N	Feet from the 3287	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.1722 Longitude -103.5111

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 1570 bbls	Volume Recovered 1560 bbls
Source of Release Rupture of tanks from lightning strike	Date and Hour of Occurrence 8/28/2015	Date and Hour of Discovery 8/28/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED



By OCD District 1 at 7:36 am, Sep 09, 2015

Describe Cause of Problem and Remedial Action Taken.*

Lightning strike at SWD facility caused rupture of tanks and release of 1570 bbls produced water. Only 10 bbls spilled off the pad area. Incoming flow onto site was shut off. Jal Fire Department extinguished the fire at site. No free liquids to recover off the pad. 3rd party consultant will travel to site to delineate horizontal and vertical impacts. A work plan will be prepared to remediate impacted area. Work plan will include excavation of impacted material onto poly liner prior to proper disposal at Sundance disposal in Eunice, NM. Clean backfill will be used once final clearance is granted.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jamon Hohensee, EOG Resources	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 09/09/2015	Expiration Date: 11/09/2015
E-mail Address: jamon_hohensee@eogresources.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag	Attached <input type="checkbox"/> 1RP-3844
Date: 9-8-15 Phone: 432-556-8074	photographs of remediation required.	

* Attach Additional Sheets If Necessary

nKJ1525227809
pKJ1525228315