

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name XTO Energy Inc.	Contact Sherry Pack
Address 200 N. Loraine, Suite 800, Midland, TX 79701	Telephone No. 432-620-6709
Facility Name Dauron 2 CTB	Facility Type Central Tank Battery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter J	Section 1	Township 21S	Range 37E	Feet from the 3535	North/South Line North	Feet from the 1980	East/West Line East	County Lea
-------------------------	---------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude **32.512441** Longitude **-103.11457**

NATURE OF RELEASE

Type of Release FLARE	Volume of Release 437	Volume Recovered
Source of Release OIL WELLS	Date and Hour of Occurrence 4/06/2015 6 AM	Date and Hour of Discovery 4/7/2015 9:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Sherry Pack	Date and Hour 4/8/2015 11 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. *

RECEIVED

By OCD District 1 at 1:13 pm, Sep 11, 2015

Describe Cause of Problem and Remedial Action Taken. *

Targa plant shut down causing us to flare. 100 mcf/d Stopped flaring 4/10/2015. Total flared 437 mcf.

Describe Area Affected and Cleanup Action Taken. *

Flaring to mitigate emissions

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: <i>Sherry Pack</i>	OIL CONSERVATION DIVISION		
Printed Name: Sherry Pack	Approved by Environmental Specialist: <i>Jan Klyger</i>		
Title: Regulatory Analyst	Approval Date: 09/11/2015	Expiration Date: ///	
E-mail Address: sherry_pack@xtoenergy.com	Conditions of Approval: ///		Attached <input type="checkbox"/> IRP 3851
Date: 5/1/2015	Phone: 432-620-6709		

* Attach Additional Sheets If Necessary

pJXK1525447511

nJXK1525447398