Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Fran	cis Dr., San	ta Fe, NM 875	05	Sa	nta Fe	, NM 87	505	-		
			Rele	ase Notific		and Co RATOR	orrective A		l Report 🔀 Final Report	
Name							Contact			
XTO Energy Inc.							Sherry Pack			
Address							Telephone No.			
200 N. Loraine, Suite 800, Midland, TX 79701							432-620-6709			
Facility Name							Facility Type			
North Seven Rivers Queen CTB							Central Tank Battery			
Surface Owner Mineral Own									API No.	
LOCATION OF RELEASE										
							South Line Feet from the East/West Line County			
м	4	22S	36E	660	So	uth 660		West	Lea	
Latitude 32.4153666 Longitude -103.276617										
NATURE OF RELEASE										
Type of Release FLARE							Release	398	Volume Recovered	
Source of Release OIL WELLS						Date and H	lour of Occurren		Date and Hour of Discovery 4/7/2015 9:45 AM	
Was Immediate Notice Given? X Yes No Not Required							Whom?		4/1/2013 3.43 AW	
By Whom?							Tomas Oberding Date and Hour			
Sherry Pack						4/8/2015 11 AAM If YES, Volume Impacting the Watercourse.				
Was a Watercourse Reached?							olume Impacting	the Watercourse		
If a Watercourse was Impacted, Describe Fully. *										
RECEIVED										
							By OCD District 1 at 1:35 pm, Sep 11, 2015			
Describe Cause of Problem and Remedial Action Taken. *										
Targa plant shut down causing us to flare. 91 mcf/d. Stopped flaring 4/10/2015. total flared 398 mcf.										
Describe Area Affected and Cleanup Action Taken. *										
		-								
Flaring to mitigate emissions										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.										
Signature: Sherry Pack							OIL CONSERVATION DIVISION			
Printed Name: Sherry Pack							Approved by Environmental Specialist: Jan Huge			
Title: Regulatory Analyst						Approval	Approval Date: 09/11/2015 Expiration Date: ///			
E-mail Address: sherry_pack@xtoenergy.com						Conditions of Approval:			Attached	
Date: 5/1/2015 Phone: 432-620-6709						///			1RP 3853	

* Attach Additional Sheets If Necessary