State of New Mexic **RECEIVED**

Energy Minerals and Natural By Jamie at 8:11 am, Sep 23, 2015

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

		OPERATOR	Initial Report	Final Report		
Name of Company: Chevron USA Inc.	Contact: Nick Hampton					
Address: 15 Smith Rd., Midland, TX, 79705		Telephone Number: Work: 575-7	704-3143 Cell: 985-	-502-2342		
Facility Name: West Dollarhide Drinkard Unit Battery		Facility Type: Battery				
Surface Owner: State surface	Mineral Owner: (QLS-091040 – State of New API No.					
	Mexico B-9613	3 LSE)				

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	24-S	38E					

Latitude: 32 deg 9.788 minutes north / Longitude: -103 deg 5.218 minutes west

NATURE OF RELEASE

Type of Release: Flare	Volume of Release: 93 MCF	Volume Recovered: 0 MCF					
Source of Release: Flare	Date and Hour of Occurrence 09/10/15 11:00AM	Date and Hour of Discovery 09/10/15 11:00AM					
Was Immediate Notice Given?	If YES, To Whom?						
🛛 Yes 🗌 No 🗌 Not Required	Kellie Jones						
By Whom? Nick Hampton							
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.						
🗌 Yes 🖾 No							
If a Watercourse was Impacted, Describe Fully.*							
N/A							
Describe Cause of Problem and Remedial Action Taken.*							
Flaring due to 3rd Party Gas Plant (Targa) Shut-In. Chevron will keep in close contact with Targa to ensure that flaring is stopped soon as they are able to							
receive our gas.							
Describe Area Affected and Cleanup Action Taken.*							
N/A							
11/21							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and							
	regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger						
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability							
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health							
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other							
federal, state, or local laws and/or regulations.	OIL CONGEDU						
	<u>OIL CONSERV</u>	VATION DIVISION					
Signature: Nick Hampton							
	Approved by Environmental Specialist:						
Printed Name: Nick Hampton	Approved by Environmental Specialist.						
	09/23/2015	///					
Title: HE Specialist	Approval Date:	Expiration Date:					
E-mail Address: cikb@chevron.com	Conditions of Approval: ////	Attached					
Date: 09/19/15 Phone: 985-502-2342		1RP 3876					
Attach Additional Shoats If Nacassary							

* Attach Additional Sheets If Necessary

nJXK1526629300