

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : Legacy Reserves Operating, LP	Contact : Daniel Rosa
Address : 303 W. Wall St. Ste 1300, Midland, TX 79701	Telephone No. : 432-631-0099
Facility Name : Rock Queen Unit # 86	Facility Type: Well
Surface Owner : STATE	Mineral Owner:
API #: 30-005-00931	

LOCATION OF RELEASE

Unit Letter E	Section 36	Township 13S	Range 31E	Feet from the 1980	North/South Line North	Feet from the 660	East/West Line West	County: CHAVES
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 33.1485596 N Longitude -103.7815247 W

NATURE OF RELEASE

Type of Release : Mixed Fluids	Volume of Release : 20 bbls	Volume Recovered: 5 bbls
Source of Release : Flow line leak	Date and Hour of Occurrence: 8/28/2015	Date and Hour of Discovery: 8/28/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour :	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

By OCD District 1 at 10:55 am, Oct 07, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A flow line leaked causing a release of 20 barrels of mixed fluids. A vac truck was called to the location and recovered 5 barrels of fluid.

Describe Area Affected and Cleanup Action Taken.* The area affected was off the well pad. Talon/LPE was contacted for initial site assessment and soil sampling to generate a work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Daniel Rosa	Approved by District Supervisor: [Signature]	
Printed Name: Daniel Rosa	Approval Date: 10/07/2015	Expiration Date: 12/07/2015
Title: Foreman	Conditions of Approval: Site samples required. Delineate and remediate as per MNOC guides. Geotag photographs of remediation required.	
E-mail Address: Drosa@legacyp.com	Attached <input type="checkbox"/> IRP-3900	
Date: 9/29/2015 Phone: 432-631-0099		

* Attach Additional Sheets If Necessary

nKJ1528038998
pKJ1528039219