

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Dan Suniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575.390.5850
Facility Name	Tomcat 21 Battery	Facility Type	Gas

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-025-33356
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	21	23S	32E	1980	FNL	1880	FWL	LEA

Latitude: 32.291774

Longitude: 103.681603

NATURE OF RELEASE

Type of Release Spill	Produced Water	Volume of Release	135 BBL	Volume Recovered	130 BBL
Source of Release	Water ran over the tops of the tank after the SCADA pack failed	Date and Hour of Occurrence	4.12.15 at 9:00 AM	Date and Hour of Discovery	4.12.15 at 9:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson BLM Tomas Oberding OCD			
By Whom?	Randy Gladden	Date and Hour 4.13.15 2:00 PM BLM 4.13.15 3:00PM OCD			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

4.12.15 Tomcat 21 Battery Devon Lease Operator arrived on location and found that 135 Bbls of produced water had ran over the tops of the tanks after the SCADA pack failed. Lease Operator pulled levels down and called vacuum truck. Spilled - 135 bbl pf produced water, Recovered 130 bbls

Describe Area Affected and Cleanup Action Taken.*

It was all contained inside unlined containment 40x40 area. Environmental group will be called to evaluate impacted area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION		
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>Kas</i>		
Title: Field Admin Support	Approval Date: 10/08/2015	Expiration Date: 12/08/2015	
E-mail Address: Jeanette.barron@dmn.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> IRP-3902
Date: 6/1/15	Phone: 575.748.1813		

* Attach Additional Sheets If Necessary

nKJ1528146835
pKJ1528147093