

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	<i>Rice Operating</i>	Contact	<i>Emmanuel Lujan - Leonardo Botello</i>
Address	<i>112 West Taylor Hobbs NM</i>	Telephone No.	<i>575-631-6914 575-393-9174</i>
Facility Name	<i>4" poly line</i>	Facility Type	<i>Flow line</i>

Surface Owner	<i>Boyd</i>	Mineral Owner		API No.	
---------------	-------------	---------------	--	---------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>27</i>	<i>22S</i>	<i>37E</i>					<i>Lea</i>

Latitude *32.36801400* Longitude *-103.14299450*

NATURE OF RELEASE

Type of Release	<i>Oil + Produce Water</i>	Volume of Release	<i>70 bbls</i>	Volume Recovered	<i>50 bbls</i>
Source of Release	<i>4" Flow line (poly)</i>	Date and Hour of Occurrence		Date and Hour of Discovery	<i>10-16-15</i>
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<i>10-16-15 12:30 pm Kellie Jones</i>		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

N/A

RECEIVED

By Kellie Jones at 1:19 pm, Nov 10, 2015

Describe Cause of Problem and Remedial Action Taken.*

A 4" poly line was hit while pushing top soil. Releasing approximately 70 bbls of oil + produce water. Line was shut in and crew cut and fused poly back together. same day.

Describe Area Affected and Cleanup Action Taken.*

The release affected approximately 75' x 25'. Panther Energy will remediate in accordance with NMOCB Regulatory Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCB rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCB marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCB acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Emmanuel Lujan</i>	OIL CONSERVATION DIVISION		
Printed Name: <i>Emmanuel Lujan</i>	Approved by Environmental Specialist: <i>Kew</i>		
Title: <i>Environmental Supervisor</i>	Approval Date: <i>11/10/2015</i>	Expiration Date: <i>01/10/2016</i>	
E-mail Address: <i>emmanuel@pantherenergy.net</i>	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCB guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 1RP-3970
Date: <i>10-20-15</i>	Phone: <i>575-631-6914</i>		

* Attach Additional Sheets If Necessary

nKJ1531448902
pKJ1531449077