

RECEIVED

By JKeyes at 8:47 am, Nov 12, 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR** Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	Red Tank 35 Federal #3 SWD Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No. 30-025-33149

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	35	22S	32E					Lea

Latitude N 32.34702° Longitude W 103.65065°**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	200 bbls	Volume Recovered	180 bbls
Source of Release	Vibration caused the nipple on the recycle line to break off	Date and Hour of Occurrence	10/14/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes, Tomas Oberding-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	10/14/2015 @ 3:13 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Vibration caused the nipple on the recycle line to break off and spill 200 bbls of produced water onto the ground. A vacuum truck recovered 180 bbls of produced water and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 70' x 60' on location inside the berm. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Dusty Wilson	Approved by Environmental Specialist:	
Title:	Environmental Advisor	Approval Date:	11/12/2015
		Expiration Date:	01/12/2016
E-mail Address:	Dusty_Wilson@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	11-9-15	Phone:	(432) 685-5771

Discrete site samples required. Delineate and remediate per NMOCD guidelines.
Geotagged photos of remediation required.

IRP 3973

* Attach Additional Sheets If Necessary