

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:08 am, Nov 13, 2015

Form C-141
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: MACHO NACHO 7 STATE SWD #001	Facility Type: SWD	
Surface Owner: State	Mineral Owner:	API No. 30-025-42463

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	7	24S	33E	2000'	North	2200'	West	Lea

Latitude 32.234001151 Longitude -103.61263191

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls	Volume Recovered: 5 bbls
Source of Release: Fiberglass Flowline	Date and Hour of Occurrence: 11/2/2015 1:30 pm	Date and Hour of Discovery: 11/2/2015 1:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A crew with C3 Pipeline struck the fiberglass flowline while constructing another line. A vacuum truck was dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in the pasture to the east of the location along the road. Repairs were made to the line and it was put back into service. C3 Pipeline has taken responsibility for the clean-up and remediation. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 11/13/2015	Expiration Date: 01/13/2016
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 3980
Date: 11/12/15 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.