State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

		OPERATOR	\boxtimes	Initial Report		Final Report
Name of Company: Holly Energy Partners (HE	Contact: Urbano Perez, Superintendent					
Address: P.O. Box 2110, Lovington, NM 88260-2110		Telephone No. 575-396-9405 (O), (575) 631-2497 (Cell)				
Facility Name: HEP Lovington Pipeline and To	Facility Type: Asphalt Loading					
Surface Owner Private, Navajo Refining Co.	Mineral Owner	N/A	A	PI No. N/A		

Surface Owner Private, Navajo Refining Co. Mineral Owner N/A

LOCATION OF RELEASE

Unit Letter SW/4	Section: 31	Township: 16S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County: Lea
---------------------	----------------	------------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.875421° N, Longitude 103.296815° W

NATURE OF RELEASE

Describe Cause of Problem and Remedial Action Taken.*				
	By Kellie Jones at 8:39 am, Dec 14, 2015			
If a Watercourse was Impacted, Describe Fully.*	RECEIVED			
Yes No				
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			
By Whom? Urbano Perez				
Was Immediate Notice Given?	If YES, To Whom?			
	Unknown	November, <u>11</u> , 2015 12 p.m.		
Source of Release Unknown	Date and Hour of Occurrence	Date and Hour of Discovery		
Type of Release Unknown	Volume of Release Unknown	Volume Recovered N/A		

While excavating for new construction, HEP discovered discolored soil with a hydrocarbon odor. Safety and Environmental Solutions (SESI) was contacted to sample and delineate. SESI mobilized onsite on 11/19/15 with Geoprobe to collect core samples for analysis. Six samples were taken from four boreholes. Results show BTEX from 0.645 to 10.8 mg/kg and TPH from 1,210 to 11,565 mg/kg. No benzene was detected and most TPH was in the diesel range.

Describe Area Affected and Cleanup Action Taken.*

The area observed as being affected is a dirt rectangle 60 ft. x 7 ft. The current owner, HEP Holly Frontier, only loads asphalt in this area but the previous operator reportedly loaded diesel and naphtha at this location. Because concrete and caliche prevented complete delineation, SESI will prepare a work plan for submittal to OCD to more completely delineate the area affected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

	OIL CONSERVATION DIVISION				
Signature: Lori Coupland Printed Name: Lori Coupland	Approved by Environmental Specialist:				
Printed Name: Lorr Coupland	per per				
Title: Director, Compliance & EHS	Approval Date: 12/14/2015 Expir	ation Date: 02/14/2016			
E-mail Address: Lori. Coupland @ hollyenergy.co	Conditions of Approval:	Attached			
Date: 12/1/15 Phone: 575.748.4076	Site samples required. Delineate and remediate as per MNOCD guides. Geota				
Attach Additional Sheets If Necessary	photographs of remediation recommend				

nKJ1534838882 pKJ1534839160

Holly Energy Partners Lovington Pipeline and Terminal



Sample Points as Flagged



Diesel Staining



Impacted Area

Holly Energy Partners Lovington Pipeline and Terminal



Sample Points as Flagged



Diesel Staining









Holly Energy Partners Lovington Pipeline and Terminal



Drain Area



Close up of Drain Area