

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APPROVED

By Kellie Jones at 8:10 am, Jan 06, 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Jeff Heath, Devon Completions Asst. Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-2274
Facility Name: Trionyx Treated Water Facility	Facility Type: Water Facility
Surface Owner: State	Mineral Owner: State
API No. NA	

LOCATION OF RELEASE

Unit Letter P	Section 2	Township 25S	Range 31E	Feet from the 723	North/South Line South	Feet from the 135	East/West Line East	County Lea
-------------------------	---------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude: **32.154003** Longitude: **-103.740557**

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 56 bbls	Volume Recovered: 56 bbl
Source of Release: Frac tank overflow	Date and Hour of Occurrence 12/18/2015, 7:00 AM	Date and Hour of Discovery 12/18/2015, 7:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD- Kellie Jones	
By Whom? Jeff Heath, Devon Completions Asst. Foreman	Date and Hour: 12/18/2015, 11:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		



REVIEWED

By Kellie Jones at 8:09 am, Jan 06, 2016

Describe Cause of Problem and Remedial Action Taken.*
Frac tanks at the Trionyx Treatment Facility overfilled due to human error causing a spill of 56 barrels of produced water to overflow inside the lined containment. Pumps were shut down at the batteries to stop the overflow.

Describe Area Affected and Cleanup Action Taken.*
56 barrels of produced water overflowed inside the lined containment at the Trionyx Treatment Facility. Liner was checked for holes and no holes were found; therefore the spill did not touch the pad or leave the lease. A vacuum truck was used to recover the entire spill of 56 barrels of produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 01/06/2016	Expiration Date: //
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: //	Attached <input type="checkbox"/>
Date: 12/22/2015	Phone: 575-746-5544	

* Attach Additional Sheets If Necessary

nKJ1600630012
pKJ1600630216



Trionyx Water Facility
56 BBLs PW 12/18/15



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: D Menoud
Map is current as of: 22-Dec-2015



Miles
0 0.02 0.04 0.07 1:3,557



Fountain Quail
WATER MANAGEMENT

WWW.FOUNTAINQUAIL.COM

R3

R382

SWABCO
TRASH TRAILERS





CAUTION
CAUSTIC

CAUTION
HYDROCHLORIC
ACID

1824





