

**RECEIVED**

By Kellie Jones at 8:48 am, Jan 06, 2016

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action****OPERATOR**☒ Initial Report ☐ Final Report

Name of Company	HERMAN L LOEB LLC	Contact	JESSE MIDDAGH OR JEREMY HAFELE
Address	P O BOX 838 LAWRENCEVILLE	Telephone No.	618-943-2227
Facility Name	POSSH TANK BAT. IL.62439	Facility Type	OIL
Surface Owner	Mineral Owner	Lease No. 3002527044	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	24S	36	E				

Latitude 32.1711 Longitude 103.2198

**NATURE OF RELEASE**

Type of Release	OIL	Volume of Release	54	Volume Recovered	54
Source of Release	Water Leg on Gun Barrel	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	12-19-2015	12-20-2015	7:30 AM
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Water leg on gun barrel froze, dump all fluid in oil tank and ran over oil tank. Called vaccum truck @ 7:30 AM Truck arrived at 1:00PM on 20th. Pulled water off of oil tanks and hauled to disposal, picked up 54 barrels oil off ground and put back in oil tank.

Describe Cause of Problem and Remedial Action Taken.\*

20' X 70' affected area.

Have a Backhoe & Vaccum truck set up for 1-5-2016 to pick up melted snow and any other fluid standing. Backhoe will then pickup wet dirt and replace with clean dirt.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

Printed Name: JEREMY HAFELE

Approved by District Supervisor:

Title: COMPTROLLER

Approval Date: 01/06/2016

Expiration Date: 03/06/2016

E-mail Address: jeremy@loeboil.com

Conditions of Approval:

Attached ☐

Date: 1/5/2016

Phone: 618-943-2227

Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.

1RP-4074

\* Attach Additional Sheets If Necessary

nKJ1600631853  
pKJ1600646125