

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 10:38 am, Jan 07, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

| | | |
|---|----------------------------|----------------------|
| Name of Company: COG Operating LLC | Contact: Robert McNeill | |
| Address: 600 West Illinois Avenue, Midland TX 79701 | Telephone No. 432-230-0077 | |
| Facility Name: LUSK DEEP UNIT A #028H | Facility Type: Battery | |
| Surface Owner: Federal | Mineral Owner: | API No. 30-025-41291 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| M | 18 | 19S | 32E | 430 | South | 300 | West | Lea |

Latitude 32.6544609 Longitude -103.8132401

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release: Oil | Volume of Release: 60 bbls Oil | Volume Recovered: 59 bbls Oil |
| Source of Release: Circulating Line | Date and Hour of Occurrence: 12/5/2015 10:30 am | Date and Hour of Discovery: 12/5/2015 10:30 am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Kellie Jones – NMOCD / Jim Amos – BLM | |
| By Whom? Amanda Trujillo | Date and Hour: December 07, 2015 3:31 PM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a Circulating line was left open while trying to move oil. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All standing fluids were able to be recovered, the facility cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|---|----------------------|---|
| Signature:  | OIL CONSERVATION DIVISION | | |
| Printed Name: Amanda Trujillo Davis | Approved by Environmental Specialist:  | | |
| Title: Senior Environmental Coordinator | Approval Date: 01/07/2016 | Expiration Date: /// | |
| E-mail Address: atrujillo@concho.com | Conditions of Approval: /// | | Attached <input type="checkbox"/> IRP 4088 |
| Date: January 5, 2016 Phone: 575-748-6940 | | | |

* Attach Additional Sheets If Necessary

nJXK1600738164
pJXK1600738239