

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy	Contact: Jerry Parker	
Address:	Telephone No. 575-396-0541	
Facility Name: Bridge State 120 Battery	Facility Type: Tank Battery	
Surface Owner State	Mineral Owner Federal	Lease No. B-1521-1

LOCATION OF RELEASE

Unit Letter G	Section: 14	Township: 17S	Range 34E	Feet from the 195	North/South Line North	Feet from the 2080	East/West Line East	County: Lea
------------------	----------------	------------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32 deg 10' 49.931"N **Longitude** 103 deg 44' 4.25" W

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 61 bbls	Volume Recovered 35bbls
Source of Release 500 Gallon Steel Tank	Date and Hour of Occurrence 9:30 AM	Date and Hour of Discovery 9:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Leking NMOCD	
By Whom? Larry Meinich	Date and Hour: 9:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Kellie Jones at 9:35 am, Jan 07, 2016



REVIEWED

By Kellie Jones at 9:35 am, Jan 07, 2016

Describe Cause of Problem and Remedial Action Taken.*
500 Gallon steel tank had internal corrosion.

Describe Area Affected and Cleanup Action Taken.*
Caliche pad and road. Backhoe was used to pick up and dispose of contaminated soil. SESI was contacted to remediate the site according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <u>Jerry Parker</u>	Approved by Environmental Specialist: 	
Title: <u>Production Foreman</u>	Approval Date: 01/07/2016	Expiration Date: //
E-mail Address: Jerry_Parker@XTOEnergy.com	Conditions of Approval: //	Attached <input type="checkbox"/> 1RP-4083
Date: 12/22/15 Phone: 575-748-1844		

* Attach Additional Sheets If Necessary

nKJ1600734216
pKJ1600734312