

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 1:12 pm, Jan 08, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Prize 27 Federal #2 CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No. 30-025-31902

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E					Lea

Latitude N 32.35706° Longitude W 103.65603°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 8 bbls produced water	Volume Recovered	0 bbls
Source of Release	Grater struck a transfer line while clearing snow	Date and Hour of Occurrence	12/30/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	12/30/2015 @ 2:59 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

While clearing snow, a transfer line was struck and leaked 2 bbls of oil and 8 bbls of produced water onto the ground. No fluids were recovered and the line was replaced/repared.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 15' off location on the entrance road. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Casey Summers	Approved by Environmental Specialist: <i>Jamie Keyes</i>		
Title: NM Environmental Advisor	Approval Date: 01/08/2016	Expiration Date: 03/08/2016	
E-mail Address: Casey.Summers@oxy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation recommended. Ensure BLM concurrence/ approval.		Attached <input type="checkbox"/> 1RP 4094
Date: 1-7-16	Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary

nJXK1600847408
pJXK1600847514