

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Energy Transfer	Contact	Phillip Little
Address	P.O. Box 1226, Jct, NM 88252	Telephone No.	325-514-2636
Facility Name	6" lateral	Facility Type	Natural Gas Gathering

Surface Owner	Jenny Chapman	Mineral Owner		API No.	
---------------	---------------	---------------	--	---------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	11	26S	37E					Lea

Latitude 32.054185 Longitude 103.135849

NATURE OF RELEASE

Type of Release	Crude Oil, Nat. Gas + Produced Water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	6" Natural Gas Gathering Line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	2:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Email to Kellie Jones on 1-18-16 from Phillip Little		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A				

RECEIVED

By Kellie Jones at 11:26 am, Jan 19, 2016

Describe Cause of Problem and Remedial Action Taken.*

Failure of a segment of 6" pipeline resulted in the release of approximately 10 bbls of a mixture of natural gas, crude oil, & produced water. Crews will dig up leak and replace 80' of 6" poly pipe on 1-18-16

Describe Area Affected and Cleanup Action Taken.*

The release affected approximately 65x90' main spot 25x40' spot
60'x3' stream to North 209'x6' stream to South
Panther Energy will remediate in accordance to NMOCB Regulatory Guidelines 40'x70' spot

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCB rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCB marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCB acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Phillip Little</i>		OIL CONSERVATION DIVISION	
Printed Name: Phillip Little		Approved by Environmental Specialist: <i>Kellie Jones</i>	
Title: Construction Specialist	Approval Date: 01/19/2016	Expiration Date: 03/19/2016	
E-mail Address: phillip.little@energytransfer.com	Conditions of Approval: Site samples required. Delineate and remediate as per NMOCB guides. Geotag photographs of remediation recommended.		Attached <input type="checkbox"/> IRP-4113
Date: 1-18-16	Phone: 575-631-2566		

Each Additional Sheets If Necessary

nKJ1601942853
pKJ1601946852