

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 1:44 pm, Feb 15, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company	Contact Ruben Garcia Assistant Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-5209
Facility Name Tomcat 15 Fed 3-2	Facility Type Injection SWD
Surface Owner Federal	Mineral Owner Federal
API No 30-025-35524	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	15	23S	32E	660	North	660	West	Lea

Latitude: N 32°31'00.80"

Longitude: W -103°66'89.38"

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 bbls	Volume Recovered 1 bbl
Source of Release 1" nipple	Date and Hour of Occurrence 2/12/16 @ 10:00 am	Date and Hour of Discovery 2/12/16 210:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones @ OCD Jim Amos @ BLM	
By Whom? Ruben Garcia Assistant Production Foreman	Date and Hour 2/12/16 @ 2:25 pm 2/12/16 @ 2:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Bull pushed bull pin into the wellhead and broke a 1" nipple causing 5 bbls produced water to release. Well was shut in to prevent further release. Nipple was replaced and well was put back to production.		
Describe Area Affected and Cleanup Action Taken.* 5 bbls produced water was released on the North, South and West side of the wellhead on the facility. 1 bbl produced water was recovered via vacuum truck. The spill was approximately 4'x15' on the West side, 6'x20' on the South side, and 4'x10' on the North side of the wellhead. All fluid remained on the pad on location. Environmental agency to be contacted for remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: <i>Jani Keyes</i>	
Title: Field Admin Support	Approval Date: 02/15/2016	Expiration Date: 04/15/2016
E-mail Address: corina.moya@dvnp.com	Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/approval.	
Date: 2/15/2016 Phone: 575.746.5559	Attached <input type="checkbox"/> IRP 4182 nJXK1604649303 pJXK1604649401	

* Attach Additional Sheets If Necessary



WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by:
Map is current as of: 15-Feb-2016



0 0.04 0.07 0.14 1:7,114

BIG CAT, 16-9 STATE FED COM 16H (DEVON ENERGY PRODUCTION CO LP)















