

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	(432) 686-3667
Facility Name	Lomas Rojas 26 #701 spill area	Facility Type	6" Water Line Riser
Surface Owner	New Mexico	Mineral Owner	New Mexico
		API No.	3002542568

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	26	25S	33E	770	North	1815	East	Lea

Latitude 32.10666 Longitude -103.5405

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	Approx. 300 bbls	Volume Recovered	180 BBLs
Source of Release	Poly line rupture	Date and Hour of Occurrence	2/18/16 approximately 12:00 am	Date and Hour of Discovery	2/18/16 approximately 12:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
<div><b>RECEIVED</b> By Kellie Jones at 10:13 am, Feb 24, 2016</div>					



Describe Cause of Problem and Remedial Action Taken.\*

A poly flow line was being moved when it contacted a 6-inch diameter poly water line riser. The riser broke at the tee. The on-site crew had a backhoe available. They were able to berm the release to keep it from spreading. Free fluids were removed with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.\*

Impacted soils will be excavated. Soil sampling will be performed to assess remaining concentrations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Zane Kurtz	Approved by Environmental Specialist: 		
Title: Sr. Environmental Rep	Approval Date: 02/24/2016	Expiration Date: 04/24/2016	
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 1RP-4190
Date: 2-24-16 Phone: 432-425-2023			

\* Attach Additional Sheets If Necessary

nKJ1605537569  
pKJ1605537897