

RECEIVED**By JKeyes at 11:12 am, Mar 28, 2016**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

XInitial Report

Final Report

Name of Company Matador Resources Company	Contact Catherine Green
Address 500 N Main St Suite 1 Roswell NM 88201	Telephone No. 575-623-6601
Facility Name Federal AF 1	Facility Type Oil

Surface Owner	Mineral Owner Federal	API No.30-025-27406
---------------	-----------------------	---------------------

LOCATION OF RELEASE


Unit Letter K	Section 18	Township 08	Range 32E	Feet from the 1980	North/South Line S	Feet from the 1980	East/West Line W	County Lea
------------------	---------------	----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude_32.7602425 Longitude -103.7907257

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 barrels	Volume Recovered 0
Source of Release tank over flowed	Date and Hour of Occurrence March 26-27, 2016	Date and Hour of Discovery March 27, 2016 11:00 am
Was Immediate Notice Given? XYes No Not Required	If YES, To Whom? Larry Brigance, foreman	
By Whom? Anthony Sanchez	Date and Hour March 27, 2016 11:30	
Was a Watercourse Reached? Yes XNo	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Pumper miscalculated volume of water in tank. Did not call for water disposal truck in timely manner. Water spilled into containment. Remediation firm will collect soil samples, remove contaminated soil and replace.		
Describe Area Affected and Cleanup Action Taken.*		
Produced water spilled to containment. Contaminated soil will be removed and replaced.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Catherine Green		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Catherine Green		Approved by Environmental Specialist: 	
Title: Regulatory Analyst		Approval Date: 03/28/2016	Expiration Date: 05/28/2016
E-mail Address: cgreen@matadorresources.com		Conditions of Approval:	
Date: March 28, 2016 623-6601		Phone: 575-	Attached 1RP 4225
		Discrete site samples only. Delineate and remediate per NMOCD guidelines.	

* Attach Additional Sheets If Necessary

nJXK1608840214
pJXK1608840286