

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 2:08 pm, Apr 05, 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Fasken Oil and Ranch, Ltd	Contact: Aaron Pachlhofer	
Address: 6101 Holiday Hill Road	Telephone No.: 432 687 1777	
Facility Name: Quail State 16 #2 SWD	Facility Type: Tank Battery/SWD	
Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No.: 30-025-39340

LOCATION OF RELEASE

Unit Letter M	Section 16	Township 20S	Range 34E	Feet from the 1230	North/South Line South	Feet from the 1980	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 32 BBL	Volume Recovered 32 BBL
Source of Release Flow line	Date and Hour of Occurrence 4/1/16, 4:00 a.m.	Date and Hour of Discovery same
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones, OCD via voice mail	
By Whom? Aaron Pachlhofer	Date and Hour 4/1/16, 11:15 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.: **A technician arrived at the Battery/SWD at 4:00a.m. and discovered the leaking flowline. The leak was isolated and stopped.**

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck removed all liquids present. Volume recovered was much higher due to precipitation on the day of the spill. Spill area will be assessed for impact after it has dried.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Aaron Pachlhofer	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 04/05/2016	Expiration Date: 06/05/2016
E-mail Address: as-opp@faci.com	Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 4232
Date: 4/4/16	Phone: 432-687-1777	

* Attach Additional Sheets If Necessary

nJXK1609650742
pJXK1609650846