

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:21 am, Apr 19, 2016

Revised October 16, 2005

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP	Contact : Mike Barrett	
Address : 1111 Bagby Street Suite 4600, Houston ,TX 77002	Telephone No. : 575-365-9724	
Facility Name : North Vacuum Abo North Unit #1	Facility Type: Battery	
Surface Owner : State	Mineral Owner:	Lease No. 30-025-24220

LOCATION OF RELEASE

Unit Letter N	Section 2	Township 17S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------------------	---------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------------------

Latitude **32.8586617 N** Longitude **-103.533493 W**

NATURE OF RELEASE



Type of Release : Unknown	Volume of Release : Unknown	Volume Recovered: Unknown
Source of Release : Unknown	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery:
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Amber Groves	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **Amber Groves with the NM State Land Office and the NMOCD required the bare spot to the west behind the battery be delineated to determine the extent of the vertical contamination.**

Describe Area Affected and Cleanup Action Taken.* **Lime Rock Resources contacted Talon/LPE to perform initial site assessment and sampling activities in order to generate a work plan.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: 	
Title: Production Superintendent	Approval Date: 04/19/2016	Expiration Date: 06/19/2016
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines. Ensure SLO concurrence/	Attached <input type="checkbox"/> IRP 4251
Date: 4/18/2016 Phone: 575-365-9724		

* Attach Additional Sheets If Necessary

approval.

nJXK1611026294
pJXK1611026421